

GAS SERVICE RECORD

This form allows the recording of the results of the required checks as defined by the Gas Safety (Installation and Use) Regulations. The information recorded on this form does not confirm that the installation was installed by a Registered Installer or that the installation complies with any Building Regulations. Chimneys / Flues were inspected visually and checked for satisfactory evacuation of products of combustion. A detailed internal inspection of the chimney/flue integrity, construction and lining has not been carried out.

HomeDoc Limited, Office 3, Fourth Floor,
81-83 Humberstone House, LE1 1WB

0116 319 5040
info@homedoc.uk



GAS OPERATIVE: J Smenja ID Card Serial No: 618686 GAS SERVICE RECORD - HMDC NO: 5451

Job Address:

Name: _____
Address: 78 Carlisle St
Leicester
Postcode: LE3 6AG Tel No: _____

Client/Landlords Details: (if different)

Name: Armani Estates
Address: 390 St. Saviours Road
Postcode: LE5 4HT Tel No: _____
Rented Accomodation: YES NO No. of appliances tested: 2

Appliance Details:

	Location	Appliance Type	Make	Model	Landlords Appliance (Yes/No)	Appliance Inspected (Yes/No)	Fuel Type: OF / RS / FL
1	Bathroom	Bowl	Ideal	Independent 2U	Yes	Yes	FL
2	Kitchen	Gas	Unknown	-	Yes	Yes	FL
3							
4							

Inspection Details:

	Operating pressure in MBAR or heat input in KW	Initial combustion analyser reading (if applicable)	Final combustion analyser reading (if applicable)	Safety device(s) correct operation (YES/NO/NA)	Ventilation provision satisfactory (YES/NO)	Visual condition of chimney/termination satisfactory (YES/NO/NA)	Flue performance checks (PASS/FAIL/NA)	Appliance serviced (YES/NO)	Appliance Safe to use (YES/NO)
1	23.8 mb	0.0003	0.0003	Yes	Yes	Yes	PASS	No	Yes
2	23.1 mb	-	-	Yes	Yes	NA	NA	No	Yes
3									
4									

Defect(s) Identified	Warning Notice Issued (YES/NO)	Remedial Action Taken
1		1
2		2
3		3
4		4

Details of work carried out: (E.g Landlord's Gas Safety Record, Service etc)

Gas installation pipework satisfactory visual inspection	YES / NO	Satisfactory gas tightness test	YES / NO / N/A
Emergency control valve (ECV) accessible	YES / NO	Protective equipotential bonding satisfactory	YES / NO

 HomeDoc Engineer Sign
  Print
  Customer Sign Tenant/Agent/Homeowner
 _____ Print
 _____ Date 20-02-23